

STANDBANK FLEET (Site #53185)

Skew Road
&, Boksburg
Gauteng
South Africa, 1459

Inspection Number: 5735823
Inspection Started: 19-09-2025, 10:03
Inspection Completed: 19-09-2025, 10:33


STANDARD BANK FLEET

Skew Road
&, Boksburg
Gauteng
South Africa, 1459

Job Number: 317
Job Reference: CA703925
Job Type: 4. Cars, LDV's and Panelvans

Passed
Overall Outcome

Internal Asset ID: CA703925
Asset Types: 4. Cars-LDV'S-Busses & Panelvans
Asset Dynamic Statuses:
Asset Attributes:
Make: FORD
Model: FIESTA 1.0 ECOBOOST TREND 5
Registration Number: CA703925
VIN Number: WF0JXXGAHJJ74492
Colour: WHITE
Fuel Type: .
Total Recon Costs: .
Mileage: .



Inspection Performed by: Gareth Dunn on 19-09-2025
Checklist: Cars/LDV'S/Panelvans & Busses - Collection Inspection

Zone: STANDBANK FLEET

None **Passed 88.9%**
Risk Level (24/28)

1. Body work: Accident/Visible damage

Check for Accident/Rust/Poor repair & Provide estimated cost (VAT Inc) if required.

Comment: All four rims damaged - R 4 000.00

Dents on rear door - R 800.00

Scratches on car - R 10 000.00

Left hand side re-sprayed

DEFECTIVE 



2. Lights - Front and Rear


Check Lights - Front and Rear

OK ✓

3. Windscreen and Windows

Check Windscreen and Windows & Provide estimated cost (VAT Inc) if required.

OK ✓



4. Wiper operation / Blades

Check Wiper operation / Blades & Provide Estimated Cost (VAT Inc) if required.


OK ✓

5. Bumpers: Visible Damage

Check Damage & Provide estimated cost (VAT Inc) if required.

DEFECTIVE ⚠


Comment: Respray of both bumpers - R 5 000.00



6. Branding Removal

Is Branding Removal required? If Branding Removal is required please provide an estimated cost (VAT Inc)

OK




7. Kilometer/Odometer Reading

Please add the Kilometer reading

OK

Comment: 130 645km



8. Valet required

Is a Valet required ? If a valet is required please provide an estimated cost (VAT Inc)

OK

Comment: VALET NEEDED (R500)

9. Interior - Dashboard/Guages/Cubby hole/Vents/Hooter

Check Dashboard/Guages/Cubby hole/Vents/Hooter & Provide estimated cost (VAT Inc) if required.

OK

10. Air conditioner/Fan


Check Air conditioner/Fan & Provide Estimated Cost (VAT Inc) if required.

OK

11. Interior - Seat/Seatbelt/Door panel/Upholstery

Check Seat /Seatbelt/Door panel & Upholstery & Provide estimated cost (VAT Inc) if required.

OK



12. Radio/Speaker/Accessories

Check Radio/Speaker/Accessories & Provide estimated cost (VAT Inc) if required.

OK

13. Central locking / Power Windows /Mirrors

Check Central locking / Power Windows /Mirrors & Provide Estimated Cost (VAT Inc) if required.

OK

14. Doors: Locks/Handles/Window Winders

Check Locks/Handles/ Window Winders & Provide estimated cost (VAT Inc) if required.

OK

15. Spare keys

Check Spare keys are present & Provide estimated cost (VAT Inc) if required.

OK

16. Spanner/Tool kit/Triangle

Check Spanner/Tool kit/Triangle & Provide estimated cost (VAT Inc) if required.

DEFECTIVE

Comment: No jack and no wheelspanner - R 1 000.00



17. Spare-Wheel

Is there a spare wheel ?

OK 



18. Licence disk

Check for valid Licence disk

OK 



19. Wheel trim/Tyre Tread RF

Check Wheel trim /Tyre Tread RF & Provide estimated cost (VAT Inc) if required.

OK 



20. Wheel trim/Tyre tread RR

Check Wheel trim/Tyre tread RR & Provide estimated cost (VAT Inc) if required.

OK 



21. Wheel trim/Tyre Tread LR

Check Wheel trim/Tyre Tread LR & Provide estimated cost (VAT Inc) if required.

OK 



22. Wheel trim/Tyre Tread LF

Check Wheel trim/Tyre Tread LF & Provide estimated cost (VAT Inc) if required.

OK 



23. Brake operation

Check Brake/Clutch operation & Provide Estimated Cost (VAT Inc) if required.

OK 

24. Shocks/Suspension

Check Shocks/Suspension/Exhaust & Provide Estimated Cost (VAT Inc) if required.

OK 

25. Transmission

Check Gearbox noise/Transmission & Provide Estimated Cost (VAT Inc) if required.

OK 

26. Battery/Starter/Alternator

Check Battery/Starter/Alternator & Provide Estimated Cost (VAT Inc) if required.

OK 

27. Engine

Check Engine noise /Performance/Leaks & Provide Estimated Cost (VAT Inc) if required.

OK 

28. Extra's

Please take a photo of the following... Canopy? Tawny Cover? Sunroof? Bull-Bar? Tow-Bar?

N/A 

Technician signature for this
Inspection:



Gareth Dunn

Approval signature for this
Inspection:



Abigail de Waal