

Inspection Report

Cars - INSP-4066-7784-1

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.1362, 28.2253

Total Cost
2 500,00

Time Tracking

Start Date	05 May 2026
Start Time	13:55
End Date	05 May 2026
End Time	14:05
Total Pause Time	00:00:00
Run Time	00:10:30
Adjusted Run Time	00:10:30

Custom Fields

MAKE:	HYUNDAI
MODEL:	STARIA 2.2D EXEC 9 Seat
REG NUMBER:	CB49FSZN
VIN NUMBER:	KMHYC811MSU205367
COLOUR:	WHITE
FUEL TYPE:	DIESEL
MILEAGE:	100115
YEAR:	2024

COMPLETED
05 May 2026, 14:05
Completed at -26.1362, 28.2253

Checklist

Uncategorized Items

Is there any physical damage on the car?

Body Work: Accident/Visible Damage

Check for any damage (Accident/Rust/Poor repair work).

Take images of any damage

Include the description for each picture captured in the notes

Response:

Pass

Captured Images:



05 May 2026, 13:56



05 May 2026, 13:56



05 May 2026, 13:57



05 May 2026, 13:57



05 May 2026, 13:57



05 May 2026, 13:57



05 May 2026, 13:57

COMPLETED
05 May 2026, 14:05
Completed at -26.1362, 28.2253

Check the front and rear lights for damage

Lights - Front & Rear

Take pictures of the lights, both front and rear

Add which lights are damaged if any in the notes

Response:

Pass

Captured Images:



05 May 2026, 13:58



05 May 2026, 13:58

Is the windscreen or any windows damaged?

Windscreen and Windows

Please check the windscreen and the windows for any damages and take images of damage

Include specifics of what is damaged in the notes section

Response:

Pass

Do the wipers & blades work, is there any damage?

Wiper Operation & Blades

Please check the wipers and the blades for any damage and ensure they operate properly

Take images if damaged, and record notes

Response:

Pass

Is there visible damage on the front and rear bumper?

Bumpers

Please check the front and rear bumpers for any physical damage. Take photo's of the damages and record details in the notes

Response:

Pass

Is branding removal required?

Branding Removal

Please check if branding has been removed. Mark as fail if not and take images of the branding

Response:

Pass

What is the reading of the odometer or hour meter?

Odometer Reading

Please record the reading and take an image of the odometer/hour meter?

Response:

100115

Captured Images:

COMPLETED
05 May 2026, 14:05
Completed at -26.1362, 28.2253



05 May 2026, 13:59

Is the odometer/hour meter working?

Odometer Hour Meter

Please check the odometer/hour meter to ensure it is working. Please take images if not

Response:

100115

Captured Images:



05 May 2026, 13:59

Is valet required?

Valet Required

Check the vehicle, if dirty mark as a fail.

Response:

Pass

Is the Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working functioning properly & are there any damages

Interior - Dashboard/gauges/cubby hole/vents/hooter

Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working

Please include additional detail in the notes

Response:


Pass

Captured Images:





05 May 2026, 14:00



05 May 2026, 14:00



05 May 2026, 14:00

Is the air conditioner/Fan working?

Airconditioner/Fan

Please check the air conditioner to ensure it is functioning.

Include details in the notes section

Response:

Pass

Are the Seat/Seatbelt/ Door Panel/Upholstery Damaged?

Interior - Seat/Seatbelt/ Door Panel/Upholstery

Check the Seat/Seatbelt/ Door Panel/Upholstery for any damage and operation

Please include details in the notes

Response:

Pass

Ensure the Radio/Speakers are working

Radio/Speakers

Please check that the radio works, and all the speakers.

Take a photo of the radio if missing or damaged.

Response:

Pass

Are the Central locking/Windows/Mirrors working, and are there any damages?

Door locks/Windows/Mirrors/Handles/ Window Winders

Please check the Central locking/Windows/Mirrors to ensure they work, and check for any damages.

Take photos of damages and record details in the notes

Response:

Pass

Does the vehicle have spare keys?

Spare Keys

Please check if the vehicle has spare key / Please take single picture with both keys if available

Response:

Fail

Note:

No spare key

Cost:

2 500,00

COMPLETED
05 May 2026, 14:05
Completed at -26.1362, 28.2253

Is the Spanner/Tool Kit/Triangle available?

Spanner/Tool Kit/Triangle

Please check if Spanner/Tool Kit/Triangle are available

Response:

Pass

Is there a Spare-Wheel?

Spare-Wheel

Response:

Pass

Is the licence disk available?

Licence Disk

Check for valid licence disk

Response:

Pass

Are the Wheel Trim /Tyre Tread RF in good condition?

Wheel Trim/Tyre Tread RF

Check Wheel Trim /Tyre Tread RF

Response:

Pass

Captured Images:



05 May 2026, 14:03

Are the Wheel Trim /Tyre Tread RR in good condition?

Wheel Trim/Tyre Tread RR

Check Wheel Trim/Tyre Tread RR

Response:

Pass

Captured Images:





05 May 2026, 14:03

Check Wheel Trim/Tyre Tread LR

Wheel trim/Tyre Tread LR

Are the Wheel Trim /Tyre Tread LR in good condition?

Response:

Pass

Captured Images:



05 May 2026, 14:04

Are the Wheel Trim /Tyre Tread LF in good condition?

Wheel Trim/Tyre Tread LF

Check Wheel trim/Tyre Tread LF

Response:

Pass

Are the brakes in good condition?

Brake Operation

Please check Brakes/Clutch operation

Response:

Pass

Captured Images:





05 May 2026, 14:04

Are the Shocks/Suspension in good condition?

Shocks/Suspension

Please check Shocks/Suspension/Exhaust

Response:

Pass

Is the Gearbox/Transmission in good condition

Gearbox/Transmission

Check Gearbox noise/Transmission

Response:

Pass

Is the Battery/Starter/Alternator in good condition/available?

Battery/Starter/Alternator

Please Check Battery/Starter/Alternator

Response:

Pass

Is the Engine running?

Engine

Check Engine noise /Performance/Leaks

Response:

Pass

..
Extras

Please take a photo of the following...

Canopy?

Tawny Cover?

Sunroof?

Bull-Bar?

Tow-Bar?

Response:

Pass



Inspection Report

Cars - INSP-4066-7784-2

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.1886, 28.2740

Total Cost
5 850,00

Time Tracking

Start Date	06 May 2026
Start Time	08:25
End Date	06 May 2026
End Time	08:29
Total Pause Time	00:00:00
Run Time	00:03:31
Adjusted Run Time	00:03:31

Custom Fields

MAKE:	HYUNDAI
MODEL:	STARIA 2.2D EXEC 9 Seat
REG NUMBER:	CB49FSZN
VIN NUMBER:	KMHYC811MSU205367
COLOUR:	WHITE
FUEL TYPE:	DIESEL
MILEAGE:	100127
YEAR:	2024

COMPLETED
06 May 2026, 08:29
Completed at -26.1886, 28.2740

Checklist

Uncategorized Items

IS TRANSPORT REQUIRED

TRANSPORT REQUIRED

Response:

No

IS THE VEHICLE IN THE SPECIFIED CONDITION

VEHICLE IN SPECIFIED CONDITION

Response:

No

Note:

No spare key R2500
Driver seat torn R850
Paint chips on bonnet & Right rear door R2500

Cost:

5 850,00

Captured Images:



06 May 2026, 08:26



06 May 2026, 08:27

Final Condition

What is the condition of the asset?

Excellent

COMPLETED
06 May 2026, 08:29
Completed at -26.1886, 28.2740

Signatures

Chad Ferguson
Assignee



SIGNED

06/05/26, 08:28
-26.19, 28.27

Chad Ferguson
Account Manager



SIGNED

06/05/26, 08:29
-26.19, 28.27

COMPLETED

06 May 2026, 08:29
Completed at -26.1886, 28.2740