

#UNKNOWN!

Vehicle Inspection Checklist



Standard Bank

VIN: VF1SSRAAC64349537YEAR: 2020REG: JS 54 JTT GP
EXPRESSIONENG NO: K7MF7104K27213MAKE: RENAULT SANDEROMODEL: SANDERO 900TBODY ST: 5DRTRANS: MANUALKMS: 202 000
202 135RUNNER: ☒ YES ☐ NODATE: 03/03/2026

SBSA ACCOUNT NO:

14 695685 0008

G = Good F = Fair P = Poor

EXTERIOR

G F P EST. COST

1. Bonnet 2 DENTS	☒	☐	☐	
2. Front	☒	☐	☐	
3. Front Bumper	☒	☐	☐	
4. Fenders	☐	☐	☐	
5. Doors	☐	☐	☐	
6. Roof	☐	☐	☐	
7. Rear	☐	☐	☐	
8. Rear Bumper	☐	☒	☐	
9. Boot /Tailgate	☐	☒	☐	
10. Trim	☐	☐	☐	
11. Fuel Door	☒	☐	☐	
12. Paint Condition	☐	☒	☐	

ELECTRICAL

G F P EST. COST

13. Power Locks	☐	☐	☐	
14. Power Seats	☐	☐	☐	
15. Power Steering	☐	☐	☐	
16. Power Windows	☐	☐	☐	
17. Audio Systems	☐	☐	☐	
18. Headlights	☒	☐	☐	
19. Taillights	☒	☐	☐	
20. Signal Lights	☐	☐	☐	
21. Brake Lights	☐	☐	☐	
22. Parking Lights	☐	☐	☐	
23. Battery	☐	☐	☐	

GLASS

G F P EST. COST

24. Windscreen	☒	☐	☐	
25. Windows	☒	☐	☐	
26. Mirrors	☒	☐	☐	
27. Rear Windows	☒	☐	☐	

INTERIOR

G F P EST. COST

28. Seats	☐	☒	☐	
29. Headliner	☐	☒	☐	
30. Carpet	☐	☒	☐	
31. Door Panels	☐	☒	☐	
32. Glove Box	☐	☒	☐	
33. Vanity Mirrors	☐	☒	☐	
34. Dashboard/ Console	☐	☒	☐	
35. Dashboard Gauges	☐	☒	☐	
36. Air Conditioning	☐	☒	☐	
37. Heater	☐	☒	☐	
38. Defroster	☐	☒	☐	

TYRES & WHEELS

G F P EST. COST

39. Tyres	☐	☒	☐	
40. Wheels	☐	☒	☐	
41. Spare Tyre	☒	☐	☐	
42. W / Spanner	☒	☐	☐	
43. Jack	☒	☐	☐	

Total Estimated Cost (Excl Vat):

RO

Notes:

HAS SPARE KEYVEHICLE
NEEDSJUMPSTART - BEEN STANDING TOO LONG

Customer Details:

Date:

Signature

SPARE KEY IN CUBBY HOLE