

Inspection Report

Cars - INSP-4199-8147-1

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.1484, 28.0438

Total Cost
9 150,00

Time Tracking

Start Date	11 May 2026
Start Time	14:12
End Date	11 May 2026
End Time	14:48
Total Pause Time	00:00:00
Run Time	00:35:33
Adjusted Run Time	00:35:33

Custom Fields

MAKE:	RENAULT
MODEL:	SANDERO 900T STEPWAY EXP
REG NUMBER:	KD96TBGP
VIN NUMBER:	VF15SRAAC67408696
COLOUR:	SILVER
FUEL TYPE:	PETROL
MILEAGE:	100248
ACCOUNT NUMBER:	20542481221

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438

Checklist

Uncategorized Items

Is there any physical damage on the car?

Body Work: Accident/Visible Damage

Check for any damage (Accident/Rust/Poor repair work).

Take images of any damage

Include the description for each picture captured in the notes

Response:

Fail

Note:

Minor scratches all round

Cost:

2 500,00

Captured Images:



11 May 2026, 14:20

Check the front and rear lights for damage

Lights - Front & Rear

Take pictures of the lights, both front and rear

Add which lights are damaged if any in the notes

Response:

Pass


Captured Images:



11 May 2026, 14:35



11 May 2026, 14:35



11 May 2026, 14:35

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438



11 May 2026, 14:35

Is the windscreen or any windows damaged?

Windscreen and Windows

Please check the windscreen and the windows for any damages and take images of damage

Include specifics of what is damaged in the notes section

Response:

Fail

Note:

W/screen chipped

Cost:

2 500,00

Captured Images:



12 May 2026, 09:39

Do the wipers & blades work, is there any damage?

Wiper Operation & Blades

Please check the wipers and the blades for any damage and ensure they operate properly

Take images if damaged, and record notes

Response:

Pass

Is there visible damage on the front and rear bumper?

Bumpers

Please check the front and rear bumpers for any physical damage. Take photo's of the damages and record details in the notes

Response:

Pass

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438

Is branding removal required?

Branding Removal

Please check if branding has been removed. Mark as fail if not and take images of the branding

Response:

Pass

What is the reading of the odometer or hour meter?

Odometer Reading

Please record the reading and take an image of the odometer/hour meter?


Response:

100248

Captured Images:



11 May 2026, 14:36



11 May 2026, 14:36

Is the odometer/hour meter working?


Odometer Hour Meter

Please check the odometer/hour meter to ensure it is working. Please take images if not


Response:

100248

Captured Images:



11 May 2026, 14:36



11 May 2026, 14:36

Is valet required?

Valet Required

Check the vehicle, if dirty mark as a fail.

Response:

Pass

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438

Is the Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working functioning properly & are there any damages
Interior - Dashboard/gauges/cubby hole/vents/hooter
Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working
Please include additional detail in the notes

Response: Pass

Captured Images:



11 May 2026, 14:24



11 May 2026, 14:25

Is the air conditioner/Fan working?
Airconditioner/Fan
Please check the air conditioner to ensure it is functioning.
Include details in the notes section

Response: Pass

Are the Seat/Seatbelt/ Door Panel/Upholstery Damaged?
Interior - Seat/Seatbelt/ Door Panel/Upholstery
Check the Seat/Seatbelt/ Door Panel/Upholstery for any damage and operation
Please include details in the notes

Response: Pass

Ensure the Radio/Speakers are working
Radio/Speakers
Please check that the radio works, and all the speakers.
Take a photo of the radio if missing or damaged.

Response: Pass

Are the Central locking/Windows/Mirrors working, and are there any damaegs?
Door locks/Windows/Mirrors/Handles/ Window Winders
Please check the Central locking/Windows/Mirrors to ensure they work, and check for any damages.
Take photos of damages and record details in the notes

Response: Pass

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438

Does the vehicle have spare keys?

Spare Keys

Please check if the vehicle has spare key / Please take single picture with both keys if available

Response:

Pass

Cost:

2 500,00

Captured Images:



11 May 2026, 14:36



11 May 2026, 14:36

Is the Spanner/Tool Kit/Triangle available?

Spanner/Tool Kit/Triangle

Please check if Spanner/Tool Kit/Triangle are available

Response:

Fail

Note:

No wheel spanner

Cost:

150,00

Captured Images:



11 May 2026, 14:28

Is there a Spare-Wheel?

Spare-Wheel

Response:

Pass

Is the licence disk available?

Licence Disk

Check for valid licence disk

Response:

COMPLETED
11 May 2026, 14:48 Pass
Completed at -26.1484, 28.0438

Are the Wheel Trim /Tyre Tread RF in good condition?

Wheel Trim/Tyre Tread RF

Check Wheel Trim /Tyre Tread RF

Response:

Pass

Captured Images:



11 May 2026, 14:37



11 May 2026, 14:37

Are the Wheel Trim /Tyre Tread RR in good condition?

Wheel Trim/Tyre Tread RR

Check Wheel Trim/Tyre Tread RR

Response:

Pass

Captured Images:



11 May 2026, 14:34



11 May 2026, 14:34

Check Wheel Trim/Tyre Tread LR

Wheel trim/Tyre Tread LR

Are the Wheel Trim /Tyre Tread LR in good condition?

Response:

Pass

Captured Images:

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438



11 May 2026, 14:34



11 May 2026, 14:34

Are the Wheel Trim /Tyre Tread LF in good condition?

Wheel Trim/Tyre Tread LF

Check Wheel trim/Tyre Tread LF

Response:

Pass

Are the brakes in good condition?

Brake Operation

Please check Brakes/Clutch operation

Response:

Pass

Captured Images:



12 May 2026, 09:39

Are the Shocks/Suspension in good condition?

Shocks/Suspension

Please check Shocks/Suspension/Exhaust

Response:

Pass

Is the Gearbox/Transmission in good condition

Gearbox/Transmission

Check Gearbox noise/Transmission

Response:

Pass

COMPLETED
11 May 2026, 14:48
Completed at -26.1484, 28.0438

Is the Battery/Starter/Alternator in good condition/available?

Battery/Starter/Alternator

Please Check Battery/Starter/Alternator

Response: Pass

Note: Battery dead

Cost: 1 500,00

Is the Engine running?

Engine

Check Engine noise /Performance/Leaks

Response: Pass

..
Extras

Please take a photo of the following...

Canopy?

Tawny Cover?

Sunroof?

Bull-Bar?

Tow-Bar?

Response: Pass

Final Condition

What is the condition of the asset? Good



Signatures

Chad Ferguson
Assignee



SIGNED

11/05/26, 14:32
-26.15, 28.04

Mordant Goolam
Regional Manager



SIGNED

11/05/26, 14:48
-26.15, 28.04

COMPLETED

11 May 2026, 14:48
Completed at -26.1484, 28.0438

Inspection Report

Cars - INSP-4199-8147-2

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.1881, 28.2741

Total Cost
6 750,00

Time Tracking

Start Date	12 May 2026
Start Time	09:39
End Date	12 May 2026
End Time	09:43
Total Pause Time	00:00:00
Run Time	00:03:37
Adjusted Run Time	00:03:37

Custom Fields

MAKE:	RENAULT
MODEL:	SANDERO 900T STEPWAY EXP
REG NUMBER:	KD96TBGP
VIN NUMBER:	VF15SRAAC67408696
COLOUR:	SILVER
FUEL TYPE:	PETROL
MILEAGE:	100278
ACCOUNT NUMBER:	20542481221

COMPLETED
12 May 2026, 09:43
Completed at -26.1881, 28.2741

Checklist

Uncategorized Items

IS TRANSPORT REQUIRED

TRANSPORT REQUIRED

Response:

No

IS THE VEHICLE IN THE SPECIFIED CONDITION

VEHICLE IN SPECIFIED CONDITION

Response:

No

Note:

Minor scratches all round R2500
W/screen chipped R2500
No wheel spanner R150
Battery flat R1500

Cost:

6 750,00

Captured Images:



12 May 2026, 09:41



12 May 2026, 09:41



12 May 2026, 09:41



12 May 2026, 09:42



12 May 2026, 09:42

COMPLETED

12 May 2026, 09:43

Completed at -26.1881, 28.2741

Final Condition

What is the condition of the asset?

Good

Signatures

Chad Ferguson
Assignee



SIGNED
12/05/26, 09:43
-26.19, 28.27

Chad Ferguson
Account Manager



SIGNED
12/05/26, 09:43
-26.19, 28.27

COMPLETED
12 May 2026, 09:43
Completed at -26.1881, 28.2741