


# Inspection Report

Cars - INSP-4466-9576-1

Times shown in: GMT+2 (Africa/Johannesburg)



## Inspection Details

Status  
**Completed**

Assignee  
**Corne Blom**

Site  
**-33.9858, 25.6042**

Total Cost  
**8 500,00**

## Time Tracking

|                   |             |
|-------------------|-------------|
| Start Date        | 02 Jun 2026 |
| Start Time        | 15:22       |
| End Date          | 02 Jun 2026 |
| End Time          | 15:30       |
| Total Pause Time  | 00:00:00    |
| Run Time          | 00:07:41    |
| Adjusted Run Time | 00:07:41    |

## Custom Fields

|             |                                |
|-------------|--------------------------------|
| MAKE:       | VW                             |
| MODEL:      | T-ROC 1.4TSi 110kW DESIGN TIPT |
| REG NUMBER: | KLH108EC                       |
| VIN NUMBER: | WVGZZA18RV182051               |
| COLOUR:     | White                          |
| FUEL TYPE:  | Petrol                         |
| MILEAGE:    | 23902                          |
| YEAR:       | 2025                           |

**COMPLETED**  
02 Jun 2026, 15:30  
Completed at -33.9858, 25.6042

## Checklist

### Uncategorized Items

#### Is there any physical damage on the car?

Body Work: Accident/Visible Damage

Check for any damage (Accident/Rust/Poor repair work).

Take images of any damage

Include the description for each picture captured in the notes

#### Response:

Fail

#### Note:

Respray rear bumper

#### Cost:

3 000,00

#### Captured Images:



02 Jun 2026, 15:23



02 Jun 2026, 15:23

### Check the front and rear lights for damage

Lights - Front & Rear

Take pictures of the lights, both front and rear

Add which lights are damaged if any in the notes

#### Response:

Pass

#### Captured Images:



02 Jun 2026, 15:24




02 Jun 2026, 15:24



02 Jun 2026, 15:24

**COMPLETED**  
02 Jun 2026, 15:30  
Completed at -33.9858, 25.6042



02 Jun 2026, 15:24

### Is the windscreen or any windows damaged?

Windscreen and Windows

Please check the windscreen and the windows for any damages and take images of damage

Include specifics of what is damaged in the notes section

Response:

Pass

### Do the wipers & blades work, is there any damage?

Wiper Operation & Blades

Please check the wipers and the blades for any damage and ensure they operate properly

Take images if damaged, and record notes

Response:

Pass

### Is there visible damage on the front and rear bumper?

Bumpers

Please check the front and rear bumpers for any physical damage. Take photo's of the damages and record details in the notes

Response:

Fail

Note:

Respray rear bumper

Cost:

3 000,00

Captured Images:



02 Jun 2026, 15:25



02 Jun 2026, 15:25

**COMPLETED**  
02 Jun 2026, 15:30  
Completed at -33.9858, 25.6042

Is branding removal required?

Branding Removal

Please check if branding has been removed. Mark as fail if not and take images of the branding

Response:

Pass

What is the reading of the odometer or hour meter?

Odometer Reading

Please record the reading and take an image of the odometer/hour meter?

Response:

23902

Captured Images:



02 Jun 2026, 15:26

Is the odometer/hour meter working?

Odometer Hour Meter

Please check the odometer/hour meter to ensure it is working. Please take images if not

Response:

23902

Captured Images:



02 Jun 2026, 15:26


Is valet required?

Valet Required

Check the vehicle, if dirty mark as a fail.

Response:


Pass




**Is the Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working functioning properly & are there any damages**  
Interior - Dashboard/gauges/cubby hole/vents/hooter  
Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working  
Please include additional detail in the notes

**Response:** Pass

**Captured Images:**



02 Jun 2026, 15:27



02 Jun 2026, 15:27

**Is the air conditioner/Fan working?**  
Airconditioner/Fan  
Please check the air conditioner to ensure it is functioning.  
Include details in the notes section

**Response:** Pass

**Are the Seat/Seatbelt/ Door Panel/Upholstery Damaged?**  
Interior - Seat/Seatbelt/ Door Panel/Upholstery  
Check the Seat/Seatbelt/ Door Panel/Upholstery for any damage and operation  
Please include details in the notes

**Response:** Pass

**Ensure the Radio/Speakers are working**  
Radio/Speakers  
Please check that the radio works, and all the speakers.  
Take a photo of the radio if missing or damaged.

**Response:** Pass

**Are the Central locking/Windows/Mirrors working, and are there any damaegs?**  
Door locks/Windows/Mirrors/Handles/ Window Winders  
Please check the Central locking/Windows/Mirrors to ensure they work, and check for any damages.  
Take photos of damages and record details in the notes

**Response:** Pass

**COMPLETED**  
02 Jun 2026, 15:30  
Completed at -33.9858, 25.6042

**Does the vehicle have spare keys?**

Spare Keys

Please check if the vehicle has spare key / Please take single picture with both keys if available

Response:

Fail

Note:

No spare keys

Cost:

2 500,00

**Is the Spanner/Tool Kit/Triangle available?**

Spanner/Tool Kit/Triangle

Please check if Spanner/Tool Kit/Triangle are available

Response:

Pass

**Is there a Spare-Wheel?**

Spare-Wheel

Response:

Pass

**Is the licence disk available?**

Licence Disk

Check for valid licence disk

Response:

Pass

**Are the Wheel Trim /Tyre Tread RF in good condition?**

Wheel Trim/Tyre Tread RF

Check Wheel Trim /Tyre Tread RF

Response:

Pass

Captured Images:



02 Jun 2026, 15:28

**Are the Wheel Trim /Tyre Tread RR in good condition?**

Wheel Trim/Tyre Tread RR

Check Wheel Trim/Tyre Tread RR

Response:

Pass

Captured Images:





02 Jun 2026, 15:29

### Check Wheel Trim/Tyre Tread LR

Wheel trim/Tyre Tread LR

Are the Wheel Trim /Tyre Tread LR in good condition?

Response:

Pass

Captured Images:



02 Jun 2026, 15:29

### Are the Wheel Trim /Tyre Tread LF in good condition?

Wheel Trim/Tyre Tread LF

Check Wheel trim/Tyre Tread LF

Response:

Pass

### Are the brakes in good condition?

Brake Operation

Please check Brakes/Clutch operation

Response:

Pass

Captured Images:





02 Jun 2026, 15:29



02 Jun 2026, 15:29

### Are the Shocks/Suspension in good condition?

Shocks/Suspension

Please check Shocks/Suspension/Exhaust

Response:

Pass

### Is the Gearbox/Transmission in good condition

Gearbox/Transmission

Check Gearbox noise/Transmission

Response:

Pass

### Is the Battery/Starter/Alternator in good condition/available?

Battery/Starter/Alternator

Please Check Battery/Starter/Alternator

Response:

Pass

### Is the Engine running?

Engine

Check Engine noise /Performance/Leaks

Response:

Pass

..  
Extras

Please take a photo of the following...

Canopy?  
Tawny Cover?  
Sunroof?  
Bull-Bar?  
Tow-Bar?

Response:


Pass



# Inspection Report

Cars - INSP-4466-9576-2

Times shown in: GMT+2 (Africa/Johannesburg)



## Inspection Details

Status  
**Completed**

Assignee  
**Corne Blom**

Site  
**-33.9307, 25.4052**

Total Cost  
**5 500,00**

## Time Tracking

|                   |             |
|-------------------|-------------|
| Start Date        | 03 Jun 2026 |
| Start Time        | 11:28       |
| End Date          | 03 Jun 2026 |
| End Time          | 11:31       |
| Total Pause Time  | 00:00:00    |
| Run Time          | 00:02:55    |
| Adjusted Run Time | 00:02:55    |

## Custom Fields

|             |                                |
|-------------|--------------------------------|
| MAKE:       | VW                             |
| MODEL:      | T-ROC 1.4TSi 110kW DESIGN TIPT |
| REG NUMBER: | KLH108EC                       |
| VIN NUMBER: | WVGZZA18RV182051               |
| COLOUR:     | White                          |
| FUEL TYPE:  | Petrol                         |
| MILEAGE:    | 23933                          |
| YEAR:       | 2025                           |

**COMPLETED**  
03 Jun 2026, 11:31  
Completed at -33.9307, 25.4052

# Checklist

## Uncategorized Items

IS TRANSPORT REQUIRED  
TRANSPORT REQUIRED

Response: No

IS THE VEHICLE IN THE SPECIFIED CONDITION  
VEHICLE IN SPECIFIED CONDITION

Response: No

Note: Respray rear bumper  
No spare keys

Cost: 5 500,00

### Captured Images:



03 Jun 2026, 11:28



03 Jun 2026, 11:29



03 Jun 2026, 11:29



03 Jun 2026, 11:29



03 Jun 2026, 11:29



03 Jun 2026, 11:30

**COMPLETED**  
03 Jun 2026, 11:31  
Completed at -33.9307, 25.4052