

Inspection Report

Cars - INSP-3819-7130-2

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.1885, 28.2741

Total Cost
10 200,00

Time Tracking

Start Date	25 Mar 2026
Start Time	12:06
End Date	25 Mar 2026
End Time	12:11
Total Pause Time	00:00:00
Run Time	00:05:05
Adjusted Run Time	00:05:05

Custom Fields

MAKE:	VW
MODEL:	CRAFTER
REG NUMBER:	KS26WYGP
VIN NUMBER:	WV1ZZZSYZN9031679
COLOUR:	WHITE
FUEL TYPE:	DIESEL
MILEAGE:	267286

COMPLETED
25 Mar 2026, 12:11
Completed at -26.1885, 28.2741

Checklist

Uncategorized Items

Is transport required?

Transport Required

Response:

No

Cost:

0,00

Is the car in the specified condition?

Inspection Pass/Fail

Mark as fail if not and provide additional information in the notes section.

Response:

Fail

Note:

Cracked w/screen R2500
2 x torn seats (R850 each)
Dent right side body panel R5000

Cost:

10 200,00

Captured Images:



COMPLETED
25 Mar 2026, 12:11
Completed at -26.1885, 28.2741

Signatures

Chad Ferguson
Assignee



SIGNED
25/03/26, 12:10
-26.19, 28.27

Chad Ferguson
Account Manager



SIGNED
25/03/26, 12:11
-26.19, 28.27

COMPLETED
25 Mar 2026, 12:11
Completed at -26.1885, 28.2741

Inspection Report

Cars - INSP-3819-7130-1

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status
Completed

Assignee
Chad Ferguson

Site
-26.0324, 28.0686

Total Cost
5 000,00

Time Tracking

Start Date	25 Mar 2026
Start Time	10:55
End Date	25 Mar 2026
End Time	11:25
Total Pause Time	00:00:00
Run Time	00:30:09
Adjusted Run Time	00:30:09

Custom Fields

MAKE:	VW
MODEL:	CRAFTER
REG NUMBER:	KS26WYGP
VIN NUMBER:	WV1ZZZSYZN9031679
COLOUR:	WHITE
FUEL TYPE:	DIESEL
MILEAGE:	267247

COMPLETED
25 Mar 2026, 11:25
Completed at -26.0324, 28.0686

Checklist

Uncategorized Items

Is there any physical damage on the car?

Body Work: Accident/Visible Damage

Check for any damage (Accident/Rust/Poor repair work).

Take images of any damage

Include the description for each picture captured in the notes

Response:

Fail

Note:

Emergency light holes
Right side body panel dented

Captured Images:



COMPLETED
25 Mar 2026, 11:25
Completed at -26.0324, 28.0686

Check the front and rear lights for damage

Lights - Front & Rear

Take pictures of the lights, both front and rear

Add which lights are damaged if any in the notes

Response:

Pass

Is the windscreen or any windows damaged?

Windscreen and Windows

Please check the windscreen and the windows for any damages and take images of damage

Include specifics of what is damaged in the notes section

Response:

Fail

Note:

W/Screen cracked

Captured Images:



Do the wipers & blades work, is there any damage?

Wiper Operation & Blades

Please check the wipers and the blades for any damage and ensure they operate properly

Take images if damaged, and record notes

Response:

Pass

Is there visible damage on the front and rear bumper?

Bumpers

Please check the front and rear bumpers for any physical damage. Take photo's of the damages and record details in the notes

Response:

Pass

Is branding removal required?

Branding Removal

Please check if branding has been removed. Mark as fail if not and take images of the branding

Response:

Fail

Note:

Branding removal needed

Captured Images:





What is the reading of the odometer or hour meter?

Odometer Reading

Please record the reading and take an image of the odometer/hour meter?

Response:

267247

Note:

267247km

Captured Images:



Is the odometer/hour meter working?

Odometer Hour Meter

Please check the odometer/hour meter to ensure it is working. Please take images if not

Response:

267247

Note:

267247km

COMPLETED
25 Mar 2026, 11:25
Completed at -26.0324, 28.0686

Captured Images:



Is valet required?

Valet Required

Check the vehicle, if dirty mark as a fail.

Response:

Pass

Is the Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working functioning properly & are there any damages

Interior - Dashboard/gauges/cubby hole/vents/hooter

Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working

Please include additional detail in the notes

Response:

Pass

Is the air conditioner/Fan working?

Airconditioner/Fan

Please check the air conditioner to ensure it is functioning.

Include details in the notes section

Response:

Pass

Are the Seat/Seatbelt/ Door Panel/Upholstery Damaged?

Interior - Seat/Seatbelt/ Door Panel/Upholstery

Check the Seat/Seatbelt/ Door Panel/Upholstery for any damage and operation

Please include details in the notes

Response:

Fail

Note:

Seats torn
Driver handle broken

Captured Images:





Ensure the Radio/Speakers are working

Radio/Speakers

Please check that the radio works, and all the speakers.

Take a photo of the radio if missing or damaged.

Response:

Pass

Are the Central locking/Windows/Mirrors working, and are there any damages?

Door locks/Windows/Mirrors/Handles/ Window Winders

Please check the Central locking/Windows/Mirrors to ensure they work, and check for any damages.

Take photos of damages and record details in the notes

Response:

Pass

Does the vehicle have spare keys?

Spare Keys

Please check if the vehicle has spare key / Please take single picture with both keys if available

Response:

Pass

Cost:

2 500,00

Captured Images:



Is the Spanner/Tool Kit/Triangle available?

Spanner/Tool Kit/Triangle

Please check if Spanner/Tool Kit/Triangle are available

Response:

Cost:



Is there a Spare-Wheel?

Spare-Wheel

Response:

Pass

Is the licence disk available?

Licence Disk

Check for valid licence disk

Response:

Pass

Are the Wheel Trim /Tyre Tread RF in good condition?

Wheel Trim/Tyre Tread RF

Check Wheel Trim /Tyre Tread RF

Response:

Pass

Captured Images:



Are the Wheel Trim /Tyre Tread RR in good condition?


Wheel Trim/Tyre Tread RR

Check Wheel Trim/Tyre Tread RR

Response:

Pass

Captured Images:



COMPLETED
25 Mar 2026, 11:25
Completed at -26.0324, 28.0686

Check Wheel Trim/Tyre Tread LR

Wheel trim/Tyre Tread LR

Are the Wheel Trim /Tyre Tread LR in good condition?

Response:

Pass

Captured Images:



Are the Wheel Trim /Tyre Tread LF in good condition?

Wheel Trim/Tyre Tread LF

Check Wheel trim/Tyre Tread LF

Response:

Pass

Are the brakes in good condition?

Brake Operation

Please check Brakes/Clutch operation

Response:

Pass

Are the Shocks/Suspension in good condition?

Shocks/Suspension

Please check Shocks/Suspension/Exhaust

Response:

Pass

Is the Gearbox/Transmission in good condition

Gearbox/Transmission

Check Gearbox noise/Transmission

Response:

Pass

Is the Battery/Starter/Alternator in good condition/available?

Battery/Starter/Alternator

Please Check Battery/Starter/Alternator

Response:

Pass


Is the Engine running?

Engine

Check Engine noise /Performance/Leaks

Response:

Pass



..
Extras

Please take a photo of the following...

Canopy?

Tawny Cover?

Sunroof?

Bull-Bar?

Tow-Bar?

Response:

Pass

Signatures

Chad Ferguson
Assignee



SIGNED

25/03/26, 11:11
-26.03; 28.07

Peter mckeen
Fleet



SIGNED

25/03/26, 11:25
-26.03; 28.07

COMPLETED

25 Mar 2026, 11:25
Completed at -26.0324, 28.0686