Inspection Report

Cars - INSP-8548-15565-1

Times shown in: GMT+2 (Africa/Johannesburg)



Inspection Details

Status	Assignee	Site	Total Cost
Completed	**Keagan Martin**	**-26.2092, 28.0531**	**2 500,00**

Time Tracking

Start Date	08 Oct 2026
Start Time	09:09
End Date	08 Oct 2026
End Time	09:22
Total Pause Time	00:00:00
Run Time	00:13:20
Adjusted Run Time	00:13:20

Custom Fields

MAKE:	TOYOTA
MODEL:	Fortuner 2.8 GD-6 Raised Body Automatic
REG NUMBER:	LC62WYGP
VIN NUMBER:	AHTJA3GS600245382
COLOUR:	SILVER
FUEL TYPE:	DIESEL
MILEAGE:	67479
YEAR:	2023

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect
Creating Accountability

Checklist

Uncategorized Items

Is there any physical damage on the car?

Body Work: Accident/Visible Damage

Check for any damage (Accident/Rust/Poor repair work).

Take images of any damage

Include the description for each picture captured in the notes

Response: Pass


Captured Images:



08 Oct 2026, 09:12




08 Oct 2026, 09:12




08 Oct 2026, 09:12



08 Oct 2026, 09:12




08 Oct 2026, 09:12



08 Oct 2026, 09:12



08 Oct 2026, 09:12



08 Oct 2026, 09:12



08 Oct 2026, 09:12

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Check the front and rear lights for damage
Lights - Front & Rear
Take pictures of the lights, both front and rear

Add which lights are damaged if any in the notes

Response: Pass

Is the windscreen or any windows damaged?
Windscreen and Windows
Please check the windscreen and the windows for any damages and take images of damage

Include specifics of what is damaged in the notes section

Response: Pass

Do the wipers & blades work, is there any damage?
Wiper Operation & Blades
Please check the wipers and the blades for any damage and ensure they operate properly

Take images if damaged, and record notes

Response: Pass

Is there visible damage on the front and rear bumper?
Bumpers
Please check the front and rear bumpers for any physical damage. Take photo's of the damages and record details in the notes

Response: Pass

Is branding removal required?
Branding Removal
Please check if branding has been removed. Mark as fail if not and take images of the branding

Response: Pass

What is the reading of the odometer or hour meter?
Odometer Reading
Please record the reading and take an image of the odometer/hour meter?

Response: 67479

Captured Images:



08 Oct 2026, 09:14


COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Is the odometer/hour meter working?
Odometer Hour Meter
Please check the odometer/hour meter to ensure it is working. Please take images if not

Response: 67479

Captured Images:



08 Oct 2026, 09:14

Is valet required?
Valet Required
Check the vehicle, if dirty mark as a fail.


Response: Pass

Is the Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working functioning properly & are there any damages
Interior - Dashboard/gauges/cubby hole/vents/hooter
Please check the Dashboard/gauges/cubby hole/vents/hooter for any damages and ensure they are working


Please include additional detail in the notes

Response: Pass

Captured Images:



08 Oct 2026, 09:15



08 Oct 2026, 09:15

Is the air conditioner/Fan working?
Airconditioner/Fan
Please check the air conditioner to ensure it is functioning.

Include details in the notes section

Response:

COMPLETED
08 Oct 2026, 09:22 Pass
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Are the Seat/Seatbelt/ Door Panel/Upholstery Damaged?
Interior - Seat/Seatbelt/ Door Panel/Upholstery
Check the Seat/Seatbelt/ Door Panel/Upholstery for any damage and operation

Please include details in the notes

Response: Pass

Ensure the Radio/Speakers are working
Radio/Speakers
Please check that the radio works, and all the speakers.

Take a photo of the radio if missing or damaged.

Response: Pass

Are the Central locking/Windows/Mirrors working, and are there any damaegs?
Door locks/Windows/Mirrors/Handles/ Window Winders
Please check the Central locking/Windows/Mirrors to ensure they work, and check for any damages.

Take photos of damages and record details in the notes

Response: Pass


Does the vehicle have spare keys?
Spare Keys
Please check if the vehicle has spare key / Please take single picture with both keys if available

Response: Fail

Note: No Spare Key

Cost: 2 500,00

Captured Images:



08 Oct 2026, 09:17

Is the Spanner/Tool Kit/Triangle available?
Spanner/Tool Kit/Triangle
Please check if Spanner/Tool Kit/Triangle are available

Response: Pass

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Is there a Spare-Wheel?
Spare-Wheel

Response: Pass

Is the licence disk available?
Licence Disk
Check for valid licence disk

Response: Pass

Captured Images:




08 Oct 2026, 09:18

Are the Wheel Trim /Tyre Tread RF in good condition?
Wheel Trim/Tyre Tread RF
Check Wheel Trim /Tyre Tread RF

Response: Pass

Captured Images:



08 Oct 2026, 09:18


Are the Wheel Trim /Tyre Tread RR in good condition?
Wheel Trim/Tyre Tread RR
Check Wheel Trim/Tyre Tread RR

Response: Pass

Captured Images:

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability



08 Oct 2026, 09:18


Check Wheel Trim/Tyre Tread LR

Wheel trim/Tyre Tread LR

Are the Wheel Trim /Tyre Tread LR in good condition?

Response: Pass

Captured Images:



08 Oct 2026, 09:19

Are the Wheel Trim /Tyre Tread LF in good condition?

Wheel Trim/Tyre Tread LF


Check Wheel trim/Tyre Tread LF

Response: Pass

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Captured Images:



08 Oct 2026, 09:19

Are the brakes in good condition?

Brake Operation

Please check Brakes/Clutch operation

Response: Pass

Are the Shocks/Suspension in good condition?

Shocks/Suspension

Please check Shocks/Suspension/Exhaust

Response: Pass

Is the Gearbox/Transmission in good condition

Gearbox/Transmission

Check Gearbox noise/Transmission

Response: Pass

Is the Battery/Starter/Alternator in good condition/available?

Battery/Starter/Alternator

Please Check Battery/Starter/Alternator

Response: Pass

Is the Engine running?

Engine

Check Engine noise /Performance/Leaks

Response: Pass

..

Extras

Please take a photo of the following...
Canopy?
Tawny Cover?
Sunroof?
Bull-Bar?
Tow-Bar?


Response: Fail

Note: Tow bar

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Captured Images:



08 Oct 2026, 09:19

Final Condition

What is the condition of the asset?	Good

Signatures

Keagan Martin
Assignee



SIGNED
08/10/26, 09:20
-26.21, 28.05

Roger Goncalves
Client / Approver



SIGNED
08/10/26, 09:22
-26.21, 28.05

COMPLETED
08 Oct 2026, 09:22
Completed at -26.2092, 28.0531

Powered by PremInspect Creating Accountability

Inspection Report

Cars - INSP-8548-15565-2

Times shown in: GMT+2 (Africa/Johannesburg)

Inspection Details

Status	Assignee	Site
Completed	**Keagan Martin**	**No location**

Time Tracking

Start Date	08 Oct 2026
Start Time	10:09
End Date	08 Oct 2026
End Time	10:10
Total Pause Time	00:00:00
Run Time	00:01:25
Adjusted Run Time	00:01:25

Custom Fields

MAKE:	TOYOTA
MODEL:	Fortuner 2.8 GD-6 Raised Body Automatic
REG NUMBER:	LC62WYGP
VIN NUMBER:	AHTJA3GS600245382
COLOUR:	SILVER
FUEL TYPE:	DIESEL
MILEAGE:	67513
YEAR:	2023

COMPLETED
08 Oct 2026, 10:10

Powered by PremInspect
Creating Accountability

Checklist

Uncategorized Items

IS TRANSPORT REQUIRED
TRANSPORT REQUIRED

Response: No

IS THE VEHICLE IN THE SPECIFIED CONDITION
VEHICLE IN SPECIFIED CONDITION

Response: Yes

Final Condition

What is the condition of the asset? Good

Signatures

Keagan Martin
Assignee



SIGNED
08/10/26, 10:10
-26.19, 28.27

Keagan
Client / Approver



SIGNED
08/10/26, 10:10
-26.19, 28.27

COMPLETED
08 Oct 2026, 10:10

Powered by PremInspect
Creating Accountability